Table 7-4 Assembly 7 steel-framed wall with adhered masonry veneer pricing analysis

rable 1-4 Assembly 1 steet-framed wall with dariered masonly verieer pricing analysis										
Assembly 7: Steel Framed Wall with Adhered Masonry Veneer										
Assembly Component		Baseline Product	Alternate (call for estimate)	Baseline Cost/ft <sup>2</sup> (incl. labor)						
			(catt for estimate)	Low	High					
INTERIOR										
1	Interior gypsum board									
2	Vapor retarder									
3	Steel-framed wall with batt	No evaluation of these components provided.								
	insulation									
4	Exterior sheathing									
5*	Air and water-resistive barrier	Fully adhered or mechanically attached sheet-applied	Fluid-applied membrane	\$1.50	\$3.50					
		membrane	system							
6*	Semi-rigid insulation	Semi-rigid mineral fiber board; 2-	No specified alternate	\$1.75	\$2.75					
	g	inch thickness		-						
4*	1	6-inch-tall clips at 24" o.c.	Stainless clips or	\$3.00	\$9.00					
		vertical; clips and girts G185 hot-	thermally improved							
	1-inch Z-girt	dipped galvanized; self-tapping fasteners	proprietary cladding support system							
	Moisture-resistant 5/8"-th									
5*	Cement backer board	taped & fastened	No specified alternate	\$2.50	\$4.00					
6*	Adhered masonry or stone	Modular (3/4" x 2-1/4" x 7-5/8")		\$39.00	\$41.00					
	veneer with grouted joints,	extruded TBX; running bond; 3/8-	Altnerate veneer							
	includes polymer modified	inch mortar joints	products							
	thin-set									
7*	Clear water repellent	Silane/siloxane blend	Antigraffiti clear water	\$1.75	\$2.50					


## Total cost to install 10,000 sq ft wall area w/easy drive-up access --> \$49,50

EXTERIOR

## Pricing Analysis Discussion

- Low and high baseline costs are based on the baseline products listed. Call for an estimate for alternate product pricing.
- Baseline costs provided will vary based on product specifics and should be used as an estimate only.
- Veneer unit prices are for typical units as noted. Pricing can vary based on size, color, and finish and should be confirmed with the unit manufacturer.
- \*See the Resource section of this guide for a list of resources related to this component.

## Assembly Plan View



EXIERIOR